

RECEIVING INSPECTION REPORT
 Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080060-7
 No. 11872
 2351 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 4-11-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT
CODE NO.

DRAWING
NUMBER

DWG. DASH OR
STANDARD PART NO.

DWG.
REV.

LOT
NO.

CLASS
NUMBER

OPER.
NUMBER

BUY OUT
CODE NO.

ACCT. OR
W.O. NO.

S.O. NO.

CHANGE TO
QUANTITY
RECEIVED

322

161

10

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

730109-9 Capacitor 1 MFD - 200V

20

Storn

REF #5307

W.E. Parker
 J.E. Parker

RECEIVED BY *Barcelos*

INSPECTED BY

XPE

DATE 4-11-57

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2351 E. COLORADO ST., PASADENA, CALIF.

No. 11874

RECEIVED FROM

DATE REC'D. 4-11-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT
CODE NO.

DRAWING
NUMBER

DWG. DASH OR
STANDARD PART NO.

DWG.
REV.

LOT
NO.

CLASS
NUMBER

OPER.
NUMBER

BUY OUT
CODE NO.

ACCT. OR
W.O. NO.

S.O. NO.

CHANGE TO
QUANTITY
RECEIVED

322

305

13

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

150

739829 Data Card

150

HE 38

REF #5356

W.E. Parker
 J.E. Parker

RECEIVED BY *Barcelos*

INSPECTED BY

XPE

DATE 4-11-57

REJECTS RETURNED
ON SHIP. MEMO NO.